




250 SE Timber Avenue, Redmond, Oregon 97756 Phone 541 923-2233 Fax 541 923-2255

SERVICE ADVISORY 016-0029

Subject: Evolution Main Gear Trailing Link Bushing

Date: May 20, 2016

In certain cases, the trailing link bushings (112-0090) have exhibited excessive wear over time. We have changed the bushing material and quality inspection methods to minimize wear of the bushing.



At the aircraft's next condition inspection (annual) we advise you to inspect these bushings for wear or slop in the trailing link. If excessive wear or slop is spotted please purchase new bushings from KCI. These bushings should continue to be inspected at each condition inspection for the aircraft.